

Operations Report

Rob Harr July 15, 2004 CDF Weekly Meeting



This Week's Stores

	7.6 pb ⁻¹ (85)	9.6 pb ⁻¹ (85)	11.4 pb ⁻¹				Total
Ongoing				83.6		3655	7/15
RF trip, TEL problems, A.G. losses → Silicon off	1884 (62)	2503 (83)	3031	79.2	25	3653	7/13
Plug calib., wet engine, trig test, TeV studies	1605 (61)	2276 (86)	2644	69.5	26	3650	7/12
Si trip, power glitch	1522 (82)	1591 (86)	1849	85.2	10	3641	7/11
L3, 3TT test, plug calib.	1997 (63)	2701 (85)	3194	81.8	31	3639	7/9
Ch159, quench	567 (83)	567 (83)	682	58.8	4	3629	7/8
Comment	Silicon [nb ⁻¹] (ε%)	Lum to tape [nb ⁻¹] (ε %)	Deliv [nb ⁻¹]	L _{init} [10 ³⁰]	Hrs	Store	Date




Downtimes, 3582 to 3588

Category	Downtime (minutes)	Lost lumi [nb ⁻¹]	Comments
Human Error	3	3054	What happens when Ace forgets to reset luminosity counter!
<u>-</u> 3	121	206	2 occurrences
Startup	55	87	Running with silicon on/off, trig table tests
Other DAQ	45	68	Plug calibration, ch 159
TeV loss	34	60	Lost RF station, lost p spike
IFIX	14	53	Plug HV monitor restart

6% deadtime, 9% downtime




PES - Saturday



Rob Harr, CDF Weekly Meeting





PES and PPR - Monday






Abort Gap After RF Station Loss





CDF acquired Luminosity (pb⁻¹)

Acquired Luminosity






Offline Summary

- The last run processed on the farm is 185082 taken on 7/13. constants are caught up to within 3 days of data taking. cdffarm2 is back. The raw data processing and calibration
- Code librarians released 6.0.0int1 for the future Gen6.
- Not for general use
- plots. Physics monitoring: Since there is nothing special, I omit the

from Tomonobu Tomura



Summary

- Good week for the accelerator.
- 2 lost stores (1 quench, 1 power glitch)
- plused magnet change out limited pbar stacking over the weekend.
- RF station loss on Wed. morning affected A.G. loss rates
- CDF ran well. Some minor problems affecting efficiency:
- Corruption of showermax lookup table
- L3 hangups
- Abort gap losses after RF station trip
- investigate during an access after this store. There's a possible problem with COT cooling. We will
- accumulator). Next shot will be mixed mode (pbars from recycler and